LumiNode / LumiCore

Release notes.

Version 2.6.1

Related products: LumiNode range, LumiCore range

With this release, Luminex introduces product improvements and bug fixes as verified with the latest Robospot controller implementations.

Improvements

■ **Improved the robustness of the discovery process on a DMX/RDM input.**

In cases where an RDM controller discovers its own RDM UID on a LumiNode DMX/RDM input.
The LumiNode now filters out discovery of RDM devices with the same UID as the RDM controller as some RDM controllers interrupt their discovery process because they see themselves as responder.

This happens for example when a controller was also connected via the network on the same universe as the DMX/RDM input of the node.

Bug Fixes

■ **Fixed incorrect RDM response times on some DMX/RDM input ports of LumiNode 12.**

- • LumiNode 12: ports 5-12.
- • LumiNode 12RJ45: ports 1,3,5,7 and 9-12.

MADE IN BELGIUM